

Proposal to improve battery contact in ALAN 441 and ALAN 443

Problem: The NiMH battery pack supplied with the stand charger set has often contact problems when inserting into ALAN 441 and ALAN443. The surrounding of the + contact is covered too much by the white plastic material and does not allow the + contact pin to enter into the gap of the battery contact in the radio's battery compartment.

Solution: Cut the surrounding plastic material around the + contact with a sharp knife. In production take care that the zone around the + contact remains free of plastic.

