


HE 6080 Umstellung 80/12 / 40 FM



← 80/12 : 220K FM40 : —
 ← FM40 : 39K 80/12 : —
 ← FM40 : 56K 80/12 : —
 — : no resistor

G8040AFA